

SS: 1033798 TBB Horton Fan Clutch replacement Cummins 300 HP

This Service Solution does not imply any special warranty coverage. Standard warranty guidelines and coverage apply. This Service Solution is provided to assist Dealers/Customers providing there will be New Fan clutch available for the Cummins 300 HP fan system. The original TBB 180220 will be replaced by TBB 219983. The PDCs will have stock of the TBB 180220 until stock runs out. If you working with a Cummins 300, make sure you read the note line, and order the TBB 219983

Applicable Vehicles

HDX

Solution:

Order the TBB 219983 Fan Clutch Horton # 462100109003