

# XENTRY TIPS

---

## Audio 20: Symbols in the status line in the central display can overlap

---

Topic number	LI82.85-P-068378
Version	1
Function group	82.85 Navigation and Communication system (CNS, ICS, COMAND, FleetBoard)
Date	07-10-2018
Validity	MODEL 292, 166, 242, 246, 156, 172, 117 with code 522+ 362+ 809
Reason for change	
Reason for block	

---

### Complaint:

The Tracking symbol can intermittently overlap with the Mute symbol and also with the CD symbol in the status line of the central display (A40/8).

Attachments	
File	Description
CD überlappt.jpg	Complaint 1
Mute überlappt.jpg	Complaint 2

### Cause:

Possibly the software release of head unit (A26/17).

### Remedy:

Perform software update of head unit (A26/17).

### Note:

- Replacing the head unit (A26/17) does not remedy the problem.
- The software is available in the market with Regio-DVD 9/2018.

Symptoms
Communication/information / Entertainment / Overall system/system error / System operable/Display faulty

Control unit/fault code		
Control unit	Fault code	Fault text
A2 / A40/3 / A26/17 - Audio or COMAND (HU5S1)	-	-