

Anti-theft alarm system (ATA) operates without obvious cause

Topic number	LI80.50-P-068392
Version	3
Function group	80.50 Anti-theft alarm system (ATA), Interior motion sensor/Tow sensor
Date	07-25-2018
Validity	A238 A205 as of MY 2019 A217 as of MY 2019
Reason for change	Remedy announced
Reason for block	

Complaint:

Anti-theft alarm system (ATA) operates without obvious cause.

False alarm may be caused by: Tow-away protection sensor.

Cause:

Possibly coding of N70 overhead control panel (OCP) control unit.

Remedy:

Perform commissioning of N70 overhead control panel (OCP) control unit.

Ensure XENTRY addon 10315 (available with DVD 05/2018) or XENTRY addon 10316 (available with DVD 07/2018).

Symptoms
Overall vehicle / Safety and locking system / Antitheft alarm system ATA / Tow-away protection / Malfunction

Operation numbers/damage codes				
Op. no.	Operation text	Time	Damage code	Note
54-0650	ON-BOARD POWER SUPPLY MAINTAIN			
54-1011	PERFORM QUICK TEST			
54-0991	PROGRAM AND CODE CONTROL UNIT N70		82566 EG	