

Air conditioning system heating instead of cooling

Topic number	LI83.30-P-068662
Version	1
Function group	83.30 Air conditioning
Date	08-14-2018
Validity	BR 177 as of SOP
Reason for change	
Reason for block	

Complaint:

The air conditioning system is blowing hot instead of cooling.

Cause:

Possible cause:

Temperature sensor in overhead control panel (OCP) delivering incorrect values.

To confirm this cause, set the air conditioning system to MAX cold. If the output is now cold, then the temperature sensor in the OCP is at fault.

Remedy:

Do not replace any parts.

The OCP/temperature sensor is being modified. The OCP will then have to be replaced in the event of complaints. As soon as new parts are available, you will be notified via this TIPS document.

Symptoms
Body / Air conditioning / Air conditioning / Insufficient cooling output