

Complaint of Fuel Odor with Model 447 with M274 Engine

Topic number	LI07.00-N-068683
Version	1
Function group	07.00 General
Date	08-21-2018
Validity	447 Metris Models with M274 engine.
Reason for change	
Reason for block	

Complaint:

Customer complaint of fuel odor. Staining or leaking present at connection between low-pressure supply line and high-pressure fuel pump.

Cause:

Possible damage to low-pressure supply line or clamp connection to high-pressure fuel pump.

Remedy:

*Note: DO NOT DISCONNECT THE LOW-PRESSURE SUPPLY LINE FROM THE HIGH-PRESSURE FUEL PUMP!

#1: Take numerous high-quality photographs of connection between low-pressure supply hose and high-pressure pump.

#2: Create PTSS case and attach photographs.

Symptoms
Power generation / Fuel system / Fuel system odor / Odor
Power generation / Fuel system / Leakage / System leaks

Validity		
Vehicle	Engine	Transmission
Vito/Metris 447	274	*