

# NEWMAR CORPORATION

## WARRANTY DEPARTMENT

# PRODUCT INFORMATION BULLETIN

DATE ISSUED	MODEL YEAR(S) AFFECTED	PIB #
10/9/2018	2018, 2019	533

### MODEL

Bay Star Sport <input type="checkbox"/>	Ventana <input type="checkbox"/>	Essex <input type="checkbox"/>
Bay Star <input type="checkbox"/>	Dutch Star <input type="checkbox"/>	King Aire <input type="checkbox"/>
Canyon Star <input type="checkbox"/>	Mountain Aire <input type="checkbox"/>	New Aire <input checked="" type="checkbox"/>
Ventana LE <input type="checkbox"/>	London Aire <input type="checkbox"/>	Other <input type="checkbox"/>

### PRODUCT INFORMATION

Newmar has created a product improvement for air conditioner plenums installed in New Aire coaches. A newly designed plenum will improve air flow from the bedroom A/C vents.

If dealing with a customer complaint involving low air flow from the rear A/C vents, follow the attached procedure to modify the existing plenum. The modification will provide the same air flow result as a new plenum.

Order the listed parts from the Newmar Parts Department:

Part Description	Newmar Part Number	Part Quantity
Aluminum Angle (1" x 1.5" x 5.5")	138740A	18
Black ABS (.60" x 2.25" x 5.5")	108200T	6
Screws (no. 8 x 3/4")	31167	50
Black Sikaflex	52760	1 Tube

**Flat Rate Code:** PIB 533

**Labor Time:** 1.5 hr.