

SERVICE BULLETIN

Classification: Reference: Date:
BT17-003b NTB17-023b December 11, 2018

2017-2019 ARMADA; OUTSIDE MIRROR(S) LOOSE AT BASE

This bulletin has been amended. See AMENDMENT HISTORY on the last page.

Please discard previous versions of this bulletin.

APPLIED VEHICLES: 2017-2019 Armada (Y62)

SERVICE INFORMATION

If the power foldable outside mirrors are manually folded/unfolded or bumped, the mirror body can become loose at the pivot point.

If this occurs, the mirrors should be adjusted again electrically before driving.

To readjust the mirrors, press the "CLOSE" switch (see Figure 1) until the mirrors are fully folded in, and then press the "OPEN" switch until the mirrors are fully open.

This mirror readjustment procedure is included in section 3 - Pre-driving checks and adjustments of the vehicle Owner's Manual.

NOTE:

- <u>DO NOT</u> replace the power foldable outside mirrors for this condition, should it occur.
- This condition is not covered under the Nissan New Vehicle Limited Warranty.




Figure 1

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
Febrauary 27, 2017	NTB17-023	Original bulletin published.
July 11, 2018	NTB17-023a	APPLIED VEHICLES section revised.
December 11, 2018	NTB17-023b	APPLIED VEHICLES section revised.

2/2 NTB17-023b