



Technical Tip

Topic	26-18-06TT - Gen III TDI - G295 - NOx Sensor Bung Mounted Off Center
Market area	United States 444 Volkswagen of America, Inc. (6444)
Brand	Volkswagen
Date	December 14, 2018

Condition

ATTENTION:
THIS IS A TECH TIP, NOT A TECHNICAL BULLETIN.
TECH TIPS ARE NOT ASSOCIATED WITH WARRANTY CLAIMING.

Gen III TDI -G295- (NOx) Sensor Bung Mounted Off Center

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Jetta, Beetle Beetle Convertible, Passat, Golf, Sportwagen	2015	2.0L TDI (CVCA, CRUA)	All	All	All

Technical Background

Some defective NOX sensor pipes in the kits when performing the 23Y8 campaign.

Service

Inspect the bung for the new NOX sensor for being mounted off-center (see attached photo). If it is and you thread in the new NOX sensor, it will destroy the new sensor. Obtain a new pipe (with correct bung installation).



Figure 1



Additional Information

Revision History		
Revision Number	Released Date	Reason For Update
2053317/1	12/14/18	Original publication.

© 2018 Volkswagen Group of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.