



Preliminary Information

PIP5572B SES or Check Engine Light with Injector Timing Related DTCs

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado	2017 - 2018	All	All	6.6 L5P	All
GMC	Sierra	2017 - 2018	All	All	6.6 L5P	All

Involved Region or Country:	North America
Condition:	Some customers may comment on a Service Engine Soon Light/Check Engine Light on.
Cause:	Technician may find any combination of DTCs P01CB, P01CC, P01CD, P01CE, P01CF, P01D0, P01D1, P01D2, P01D3, P01D4, P01D5, P01D6, P01D7, P01D8, P01D9, P01DA, P02CC, P02CD, P02CE, P02CF, P02D0, P02D1, P02D2, P02D3, P02D4, P02D5, P02D6, P02D7, P02D8, P02D9, P02DA, P02DB set.

Correction:

Check for any open recalls, service updates or campaigns on the vehicle.

If recalls, service updates or campaigns are open perform those and use the corresponding labor operations to close those out.

If there are no open recalls, service updates or campaigns and the vehicle is a 2018 model year check for and perform any available ECM calibration updates.

If there are no open recalls, service updates, campaigns or ECM calibration updates, refer to service information for diagnosis of the concern.

If the vehicle is a 2017 model year and there are no available ECM calibration updates, open recalls, service updates or campaigns please clear the DTC and return the vehicle to the customer. GM engineering is aware of the concern and is investigating. Use Labor operation 4029959 for Emissions - Customer Concern Not Duplicated.

Warranty Information

Labor Operation	Description	Labor Time
4029959	Emissions - Customer Concern Not Duplicated.	Use Published Labor Time

Version History

Version	3
Modified	06/26/2018 - Created 9/25/2018 - Updated to add labor operation 12/04/2018 - Updated to refer to service update N182179090 for 2018

model year vehicles and to use labor operation 4029959 Emissions -
Customer Concern Not Duplicated (CCND) for 2017 model year vehicles.



© 2019 General Motors. All Rights Reserved.