



Technical Journal

TITLE:

Squealing noise from rear brakes at low speed. 17"

REF NO: TJ 33506.2.0	ISSUING DEPARTMENT: Technical Service	CAR MARKET: United States and Canada	
PARTNER: 3 US 7510 Volvo Car USA		ISSUE DATE: 2018-03-07	STATUS DATE: 2018-03-12
FUNC GROUP: 5120	FUNC DESC: Rear wheel brake	Page 1 of 2	

“Right first time in Time”

Attachment

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
234							2017-2017		-	201617-201722
235							2017-2018		-	201620-201722
236							2017-2018		-	201646-201722
238							2017-2018		-	201646-201722
246							2018-2018		-	201717-201722
256							2016-2018		-	201505-201722

CSC Customer Symptom Codes

Code	Description
1P	Brakes/Unusual noise/Rear

VST Operation Number

DTC Diagnostic Trouble Codes

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

Text

**DESCRIPTION:**

*Added Vehicle Type

If squealing noise occur from rear brakes 17" at low speed, follow advice under service.

SERVICE:

If symptom is confirmed, follow advice in VIDA regarding greasing method when changing the brake pads.

VEHICLE REPORT:

Yes, if the solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 5122.

Please include a video or sound recording of the noise, include speed, weather conditions and other observations in the vehicle report.