VOLVO CAR SERVICE AND PARTS BUSINESS



# **Technical Journal**

## TITLE: Volvo logo on steering wheel, replacement

REF NO:	ISSUING DEPARTMENT:		ARKET:
TJ 31750.3.0	Technical Service		s and Canada
3 US 7	PARTNER:	ISSUE DATE:	STATUS DATE:
	/510 Volvo Car USA	2018-03-08	2018-03-12
FUNC GROUP: 8863	FUNC DESC: Frontal airbag driver	Page <sup>-</sup>	1 of 12

## "Right first time in Time"

## Attachment

File Name	File Size
TJ 31750 repair.pdf	2.2940 MB
TJ31750.pdf	0.2113 MB

## Vehicle Type

Туре	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
124							2011-2016		0113001-0200260	200920-201614
134							2011-9999		0000194-0999999	201020-999952
135							2010-2010		0118001-0377263	200920-201020
136							2010-2016		0074001-0274097	200920-201619
138							2016-9999		0000122-0999999	201345-999952
155							2011-9999		0001147-0999999	201035-999952
156							2010-2017		0084237-1232863	200946-201735
157							2015-9999		0000022-0999999	201450-999952
275							2011-2014		0568001-0707110	201020-201428
533							2011-2013		0220000-0312066	201020-201251
542							2011-2013		0107000-0144301	201020-201325
544							2011-2012		-	201020-201219
545							2011-2012		0509000-0700628	201020-201219

Produced in the USA and available as an electronic document. Hard copy documents are printed in USA on recycled paper containing a minimum of 50% wastepaper and 10% post-consumer waste. © 2018 VOLVO CAR USA, LLC



#### **CSC** Customer Symptom Codes

Code	Description
R9	Steering wheel/Steering wheel trim appearance

#### VST Operation Number

VST Operation Number	Description
98634-2	Steering wheel emblem replace acc. to TJ31750

## DTC Diagnostic Trouble Codes

Rows beginning with \* are modified Note! If using a printed copy of this Technical Journal, first check for the latest online version.

## Text

#### **DESCRIPTION:**

\* Model year in repair method has been updated.

If the Volvo logo on the center of the steering wheel is peeling off or corroded, the logo itself can now be replaced (no need to replace the whole airbag unit). See picture "TJ31750.pdf".

#### **SERVICE:**

Replace carefully the Volvo logo according to repair method "TJ 31750 repair.pdf". (Masking tape: any suitable can be used)

#### **VEHICLE REPORT:**

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 8863.

To view TJ attachment continue to next page. This TJ has two attachments.

VOLVO	/olvo Car Customer Service	TJ 3	1750
Title	Steering wheel emblem	Page	1(9)
Action	Replacement	Operation number:	98634-2

## Affected vehicles

Model year	Model
2013, 2014, 2015	S60 (11-)
2016	S60 Inscription
2011, 2012, 2013, 2014, 2015	S80 (07-)
2011, 2012,	S40, V50,
2011, 2012, 2013	C30, C70
2015	V60
2010, 2011, 2012, 2013, 2014, 2015	XC60
2011,2012, 2012, 2013, 2014, 2015	XC70 (08-)
2011, 2012, 2013, 2014	XC90

		Materials	
Materials	Qty.	Part No.	Notes
Cleaning agent	0.1	9192678	

,


## TJ Instruction VCC-496167-2


Materials				
Materials	Qty.	Part No.	Notes	
Primer	1.0	1161727	CA;	
Primer	1.0	31480527	US;	
Emblem	1.0	31467395		

Special tools			
Description	Part No.		
Feeler gauge	981 4120		


## Page 2 (9)

#### Information






#### **Orientation view**




#### Color symbols




Note! This colour chart displays (in colour print and electronic version) the importance of the different colours used in the images of the method steps.


- 1. Used for focused component, the component with which you will do something.
- 2. Used as extra colors when you need to show or differentiate additional parts.
- 3 . Used for attachments that are to be removed/installed. May be screws, clips, connectors, etc.
- 4 . Used when the component is not fully removed from the vehicle but only hung to the side.
- ${\bf 5}$  . Used for standard tools and special tools.
- 6 . Used as background color for vehicle components.

#### Removal








## TJ 31750




#### Installation








## TJ 31750





Caution! Make sure that equal pressure is applied to the full length of the component.

Caution! Make sure that the surface is at a minimum temperature of 20°C.





