

XENTRY TIPS

No difference between blower setting 5 and 6 on air conditioning system

Topic number	LI83.30-P-069074
Version	1
Function group	83.30 Air conditioning
Date	11-19-2018
Validity	Model series 190 with code 494 (USA)
Reason for change	
Reason for block	

Complaint:

No difference between blower setting 5 and 6 on air conditioning system.

Cause:

Possible software irregularity

Remedy:

Implementation of software update (software A 190 902 16 03) of control unit N22/1. The software may need to be requested through XSF.

Symptoms
Body / Air conditioning / Air conditioning / Insufficient cooling output

Control unit/fault code		
Control unit	Fault code	Fault text
N22/1 - Air conditioning (AAC) (HVAC190)	-	-