

Service Campaign Bulletin



Mercedes-Benz

Campaign No. 2018090015, November 2018

TO: ALL MERCEDES-BENZ CENTERS

SUBJECT: **Model G65 AMG vehicles (463 platform)**
Model Year 2018
Replace left air filter housing with bleed line

Daimler AG ("DAG"), the manufacturer of Mercedes-Benz vehicles, has determined that on certain MY18 G65 AMG vehicles, the purge air line for the left air filter housing may not meet US market specifications. An authorized Mercedes-Benz dealer will replace the left air filter housing on the affected vehicles.

Prior to performing this Service Campaign:

- Please check VMI to determine if the vehicle is involved in the Campaign and if it has been previously repaired.
- Please review the entire Service Campaign bulletin and follow the repair procedure exactly as described.

Approximately 6 vehicles are affected.

Order No. P-SC-2018090015

This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Quality Records.

Service Campaign Bulletin

Service Campaign Bulletin

Service Campaign Bulletin

Service Campaign Bulletin

Service Campaign Bulletin

Procedure

1. Replace left air filter housing (A, figure 1) with bleed line (AR09.10-P-1150MUC).




Figure 1

Primary Parts Information

Qty.	Part Name	Part Number	Estimated Replacement Rate
1	Air filter housing (damper filter)	A 279 090 33 00	100%

Warranty Information

Operation: Replace left air filter housing with bleed line (02-2419)

Includes: Drain/fill cooling system

Damage Code	Operation Number	Labor Time (hrs.)
09 910 34 7	02-2419	1.4

i Note

Operation Number labor times are subject to change.