



Service Bulletin #081418

Code #9014

RM2652 Refer in sl-out w/fan

August 30 2018

This bulletin is in reference to the **11' & 19' Ranger's/Laredo's**, and the **16' Laredo**. All would have refrigerators in the slide-out.

Dates involved – Trailers invoiced between 9/25/17 to 8/3/18

Reason for bulletin – It has come to our attention that some of these trailers do not have the 12 volt circulating fan installed on the refrigerator as is required by manufacturer when installed with two side vents.

Inspection needed – Please remove upper side refer vent, fan (if present) will be mounted between upper and lower coils.

Action needed – If no fan is present please contact your **Bison Customer Service Representative (574-658-4161)** for needed parts.

Parts needed – **Dometic part # 3316331.000**, this kit includes all parts and instructions needed to complete installation.

Flat Rate Allowed – Inspection only .1 hour. Inspection and installation 1 hour.

Bison Coach apologizes for this inconvenience as we continue to strive for Excellent Customer Service.

Sincerely,