

L73X-
A.11.18

To: Official After-Sales Network
Subject: 1-999 Plate Replacement
Date: 07 December 2018
Pages: 3



Campaign Code:

L73X-A.11.18

Campaign Name:

1-999 Plate Replacement

Model:

Aventador SV J

Model Year:

MY 19

Special or limited editions:

All

Markets:

All

VIN Identification:

From **KLA08069** to **KLA08275**

..KLA08069	..KLA08135	.. KLA08186
..KLA08092	.. KLA08161	.. KLA08258
..KLA08128	.. KLA08166	.. KLA08272
.. KLA08129	.. KLA08176	.. KLA08275

Important: before proceeding with the repair, connect to the warranty portal and use VIN Info to check that

- the vehicle is actually affected by the instructions given in this bulletin; some vehicles may not be, even when their VIN is included.
- Procedures are identified by a letter (e.g. A, B or C....etc., whose differences will be explained later in this bulletin); make sure that the spare parts corresponding to the assigned procedure are used.

Example

VIN	17 DIGIT VIN	Model	MODEL NAME	Warranty Start Date	DD/MM/YYYY	Warranty End Date	DD/MM/YYYY
Total days of workshop repairs: 0							
Prior activated CPO list							
CPO ?	Validity months	Classification	Mileage	Insertion date	Approval date	Start date	Expire date Claim status
<div style="text-align: center;"> Page 0 of 0 Rows </div>							
Available Campaigns							
Campaign Code	Campaign Type	Procedures	Campaign Description	Campaign Starting Date	PDF	AV	
LXX-A-XXXX	A- Service Action	B	CAMPAIGN NAME	DD/MM/YYYY			



NOTE:

Procedure A will be available only when the instructions require a preliminary check to be performed to determine whether or not the vehicle actually needs updating.

Information to the field:

As a result of ongoing product monitoring, Automobili Lamborghini S.p.A. requests to replace the SV J plate on the specified vehicles.

Solution for the network:

Update the vehicle, following the instructions given in this bulletin.

Replacement parts:

Order the following codes required for the specified operation:

- Operation B – 1-999 Plate Replacement

Code	Description	Q
470000107H	SV J Plate	1

Management of replaced parts.

Store the parts removed from the vehicle in a suitable manner, marked with their barcode for identification during visits by the competent Area Manager.

Labor

- Operation B: 0.1 hour


Bulletins superseded.

None.

Warranty instructions.

To request reimbursement for the corrective action performed, access the Warranties section of the Lamborghini Portal and follow the “Campaigns” entry instructions in the W.Claim manual which can be downloaded from the Portal.

Select the required campaign and proceed with entry, carefully reading the options present in the alert displayed by the system (see example) and select the option performed on the vehicle.



Depending on the option performed, the reimbursement will be structured in the following manner:

- OPTION B – 1-999 Plate Replacement
 Labor: 0.1 hour
 spare parts: 470000107H



WARNING!

Attach all documents generated during the work carried out as evidence of the work itself, for instance workshop orders, diagnostic protocols etc. If one or more of these is missing it may lead to a rejected reimbursement request.

Fill out the Service and Recall Campaign section in the warranty booklet, which is shown in the figure below.

Tools/Materials required

Code	Description.	Q



IMPORTANT:

Before performing the repairs specified in the service campaign, the SD-Creator program must be installed. SD-Creator installation instructions are contained in the bulletin “BI.09.17 [ENG]_SD-Creator installation package procedures”.



N.B. (*)

All ODIS technical documentation can be viewed on the Lamborghini web portal, in the corresponding ODIS section.



Technical Procedure

Operation B - SV J plate replacement

1. Identify the SV J plate to replace in the dashboard-front side window on the driver's side.

Remove the two screws and remove the plate to be replaced.

Position the correct SV J plate and tighten the 2 screws.

Tighten the screws.

Tighten by **hand**.



For more information, contact the Technical Support.