

Auto High Beam System Indicator, Fog Lights, and Automatic Intermittent Wipers Not Working; Lighting Setup Menu Issues

AFFECTED VEHICLES

| Year | Model | Trim | VIN Range |
|---------|-------|--------------|-----------|
| 2017-19 | CR-V | EX and above | ALL |

EDITOR'S NOTE: This article revises the one posted in **March 2018**.

When installing the shipping fuses, **never** do it with the engine running. If you do, you could wind up with any of these issues:

- With the headlight switch in AUTO, the Auto High Beam System indicator won't come on.
- With the headlight switch in AUTO, the fog lights won't come on with the low beam headlights on.
- The automatic intermittent wipers won't work.
- The **Lighting Setup** menu under **Vehicle Settings** is missing settings (there are just two instead of five).



- The **Headlight Auto Off Timer** setting doesn't respond when selected.

If this is the case, following these steps should restore things to normal:

1. Turn the ignition to OFF.
2. Remove the No. 18 BACKUP (10 A) fuse from the under-fuse/relay box.
3. Wait a few minutes, then install the fuse.