



Preliminary Information

PIC6009B Sway Bar Not Present on Vehicles Equipped with 4-Wheel Independent Suspension (RPO FE1)

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Corvette	2014 - 2019	All	All	LT1	All

Equipped with 4-Wheel Independent Suspension (RPO FE1)

Supersession Statement

This PI was superseded to update Model Years. Please discard all copies of PIC6009A.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition / Concern

A dealer or customer may inquire as to whether or not a rear sway bar can be added to a vehicle that was not originally equipped with one. The rear sway bar is part of the Z51 Performance Package.

Recommendations / Instructions

Important: GM does NOT recommend or support this modification. Do NOT install a rear sway bar on a vehicle not originally equipped with the Z51 Performance Package.

The FE1 suspension system was designed and tested without a rear sway bar. Installing a rear sway bar on a FE1 (non-Z51) vehicle may cause concerns with vehicle control, ride and handling.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

