

Subject Clad Wheel Finish Peeling off/BubblingOff/Bubbling		Market USA
Service Category Suspension	Section Tire/Wheel	
Applicability 2014-2020 Highlander 2020 Sienna		


APPLICABLE VEHICLES

2014-2020	Highlander	2020	Sienna
2014-2020	Highlander HV		

CONDITION

Some Highlander and Sienna clad/chrome wheels might experience bubbling and/or peeling off on the wheel coating (see picture below). Table below shows the wheel part numbers affected by the issue.

Model Year/Model	Part Number
14-20MY	4260D-0E010
Highlander/Highlander HV	4260D-0E020
20MY Sienna	4260D-08010
	4260D-08020
	4260D-08030
	4260D-08040



NOTE: Wheel blemishes caused by this process are non-warrantable

RECOMMENDATIONS

During stick-on wheel weight removal process, some technicians may utilize a heat gun to make weights flexible. The excessive heat from the heat gun causes the wheel coating to peel off and/or bubble. Do not utilize any heat tool to remove stick-on wheel weights.

LINK REFERENCES

This Tech Tip does not contain any link references