

Latest Vehicle Concern Fixes



Reverse Mirror Dip Feature Inoperative	E-PACE 19MY
<p>Customer Voice:</p> <ul style="list-style-type: none">Customers may report that the reverse dip mirror feature is not working upon selecting reverse. <p>Technical Description:</p> <ul style="list-style-type: none">This may be caused by a Car Configuration File (CCF) error. <p>Status:</p> <ul style="list-style-type: none">TSB JTB00683NAS1 will be published to address this issue, should a customer express a concern please refer to this TSB.	

