


Latest Vehicle Concern Fixes



Incorrect Function of Climate Seat Control from Touchscreen	I-PACE 19MY
<p>Customer Voice:</p> <ul style="list-style-type: none">A customer may express a concern that after selection of the seat squad icon on the Touchscreen, the function turns on, then off again. <p>Technical Description:</p> <ul style="list-style-type: none">This may be caused by a Car Configuration File (CCF) error. <p>Status:</p> <ul style="list-style-type: none">TSB JTB00681NAS1 will be published to address this issue, should a customer express a concern please refer to this TSB.	 <p>The diagram shows the climate control panel with five numbered callouts: 1 points to the fan speed control, 2 points to the front passenger seat heater control, 3 points to the front driver seat heater control, 4 points to the rear seat heater control, and 5 points to the temperature control dials.</p>

