

# Latest Vehicle Concern Fixes



## Windshield Water Leaks

### Customer Voice:

- Customers may report that water is leaking into the cabin from the top of the windshield.

### Technical Description:

- The windshield may not be completely sealed across the top edge due to a manufacturing issue.

### Status:

- Service Action N292 will be published to proactively check the windshield sealing on Discovery vehicles in Canada.
- Exact timing for publication is depending on adequate parts supply and is to be determined at this point.

## Discovery 17MY

