



Preliminary Information

PIP5526A PQC 2015-2018 8L45 8L90 Automatic Transmission Park Actuator Rod Restriction has ended.

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Cadillac	ATS Models	2016 - 2018	All	All	All	M5N, M5T, M5U
Cadillac	CT6 Models	2016 - 2018	All	All	All	M5N, M5X
Cadillac	CTS Models	2016 - 2018	All	All	All	M5N, M5U
Cadillac	Escalade Models	2015 - 2018	All	All	All	M5U
Chevrolet	Camaro	2016 - 2018	All	All	All	M5T, M5U
Chevrolet	Corvette	2015 - 2018	All	All	All	M5U
Chevrolet	Colorado	2017 - 2018	All	All	All	M5T
Chevrolet	Express	2017 - 2018	All	All	All	M5U
Chevrolet	Silverado	2015 - 2018	All	All	All	M5U
GMC	Canyon	2017 - 2018	All	All	All	M5T
GMC	Savana	2017 - 2018	All	All	All	M5U
GMC	Sierra	2015 - 2018	All	All	All	M5U
GMC	Yukon Models	2015 - 2018	All	All	All	M5U

Involved Region or Country	North America
Additional Options (RPO)	None.
Condition	The 8L45 and 8L90 8 Speed Transmission Park Pawl Actuator Rod (Part numbers 24273627, 24273628, 24274277, 24276682, 24276683, 24279983, 24279985, 24279987, 24279988, 24279989) restriction has ended.
Cause	PIP5526 has been replaced by bulletin 19-NA-035 .

Correction:

Your cooperation with this program was greatly appreciated.

Version History

Version	1
Modified	10/16/2017 - Created on 03/14/2019 Updated to end the part restriction.



GENERAL MOTORS

© 2019 General Motors. All Rights Reserved.