

Reference	SSM74298
Models	Range Rover Evoque / L551
Title	L551 20MY Diagnostic Trouble Code B1974-86 stored in the Body Control Module
Category	Electrical
Last modified	21-Feb-2019 00:00:00
Symptom	205000 Electrical Accessories

Content **Issue:**
During or after the Pre Delivery Inspection (PDI) a technician may observe that Diagnostic Trouble Code (DTC) B1974-86 – Rear View Mirror Module Signal Invalid is stored in the Body Control Module (BCM) as a permanent DTC and cannot be cleared.

Cause:

A software error in the Rear View Mirror Module (RVMM) is causing B1974-86 to be permanently flagged in the BCM.

- The DTC has no functionality effect on the vehicle and there are no additional warnings displayed in the vehicle.

JLR engineering are developing a software release to rectify the concern and this will be subject to a further communication.

Action:

1. Using the Jaguar Land Rover approved diagnostic equipment, check the BCM for any clear sight rear view mirror module communication related DTCs.
2. If no additional DTC's are stored and no issues are observed with clear sight rear view activation or deactivation please release the vehicle to the customer as no further action is required.
3. If additional rear view mirror DTC's are logged and/or functionality concerns are observed with the clear sight rear view mirror please diagnose as required and perform the recommended corrective actions.

Please refer to Topix section 100.00 – Description and Operation – Diagnostic Trouble code Index – Body Control Module (BCM) for further DTC information.

NOTE: For DTC B1974-86 – Do not replace the Clear Sight Rear View Mirror