

Service Bulletin

Bulletin No.: 19-NA-048

Date: March, 2019

TECHNICAL

Subject: Metallic Hiss/Rattle Noise Heard From Front Of Vehicle

Brand:	Model:	Model Year:		VIN:		Engino	Transmission:
		from	to	from	to	Engine:	1141151111551011.
Chevrolet	Blazer	2019	2019				

Involved Region or Country	North America and N.A. Export Regions		
	Some customers may comment that a metallic hiss or rattle type noise can be heard coming from the front of the vehicle. Some technicians may notice:		
Condition	The noise is present at all speeds, but is most noticeable at low speed driving with some throttle input.		
	 The noise is present in all gears and is a constant frequency even with increasing engine speed. 		
Cause	This condition may be caused by the transmission range selector lever cable transmission range selector lever range sele		
Correction	If the noise has been verified to be coming from the shift cable, replace the cable with a new design cable that has added mass for noise dampening.		

Service Procedure

Refer to Automatic Transmission Range Selector Lever Cable Replacement in SI.

Parts Information

Use the vehicle identification number (VIN), and the GM Electronic Parts Catalog to determine the proper cable to order.

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time		
8460240	Automatic Transmission Range Selector Lever Cable Replacement	0.6 hr*		
* The May 1 update of the Labor Time Guide will contain this change.				

Version	1
Modified	Released March 20, 2019

