
Reference	SSM74346
Models	Range Rover / L405
Title	Heated seats don't function, after installing a new Seat Heater Control Module
Category	Body
Last modified	28-Mar-2019 00:00:00
Symptom	101000 Seating
Content	<p><u>Issue:</u> Heated seats don't function, after installing a new Seat Heater Control module.</p> <p><u>Cause:</u> LR113824 & LR122451 have the wrong level of software. Applicable to 18 MY only.</p> <p><u>Action:</u> Please raise a TA so that the JLR engineering team can send you a Seat Heater Control module with the correct level of software.</p>