

# SCRAMBLER 1200 CRUISE CONTROL FUNCTION TEST



## Notice Information

Ref	10061
Posted Date:	
Posted To:	Technician, Aftersales Manager, Service Leader / Advisor, Accounts / Admin
Subject:	Service/Technical

**TOL NOTICE (US&CAN) – March 4, 2019**

**TOL Ref. # 10061-SVC**

## Scrambler 1200 Cruise Control Function Test

Triumph has become aware of a Triumph Diagnostic Tool software issue which is preventing the cruise control function test from appearing in the function test menu when connected to a Scrambler 1200 XC or XE model. We are currently working on a fix for this issue and will keep you updated as soon as a solution is available.

In order for the engine ECM to allow cruise control to function, it needs to detect that each of the cruise-related switches are working correctly. The TDT function test is simply a 'wizard' to prompt each of the switch operations. It does not directly configure the ECM and does not need to be used in order for the switch check to be carried out.

In the event that you encounter DTC P1575 "Cruise control disabled until button press sequence completed" prior to the next TDT release, please follow the procedure outlined below:

1. Switch the ignition on and ensure that the kill switch is in the 'run' position
2. Activate each cruise control related switch in turn:
  - Front brake switch
  - Rear brake switch
  - Clutch lever switch
  - Twist grip cruise cancel switch (operated by holding the twist grip in the fully closed position)
  - Cruise control ON/OFF switch
3. Check and clear the DTC
4. Test ride and confirm that cruise control is operating normally

If you have any further questions, contact Triumph Customer Support at (888) 284-6288.