

NEW DIAGNOSTIC SOFTWARE AVAILABLE FOR DOWNLOAD



Notice Information

Ref	10288
Posted Date:	
Posted To:	General Manager / Business Owner, Technician, Aftersales Manager, Service Leader / Advisor, Accounts / Admin
Subject:	Service/Technical

TOL NOTICE (US&CAN) – March 26, 2019
Ref. # 10288-SVC

TOL

New Diagnostic Software Available for Download

Diagnostic software version **2019-3** is now available to download. Dealers should download this update from your Triumph Diagnostic Software page under the Service/Technical menu and begin using immediately.

- Please ensure all new bikes have the latest software downloaded at PDI.
- Please ensure all bikes being serviced have the latest software downloaded.
- Please ensure all relevant staff are informed of this update.

****PASSWORD CHANGE: New Password: (case sensitive): Moto219**

SUMMARY OF CHANGES:

1	New Software Functionality:	NA
		New calibrations: Thruxton TFC
		• 030245-01
		• 030246-01
		• 030248-01
		Updated calibrations: Scrambler 1200 XC
		• 030249-02
		• 030250-02
2	Engine ECM Calibrations:	• 030251-02
		• 030252-02
		Updated calibrations: Scrambler 1200 XE
		• 030253-02
		• 030254-02
		• 030255-02
		• 030256-02
		Tiger 1200 fuel injector calibration:
		• 030274-01
3	Chassis ECM Calibrations:	Updated calibrations for:
		• Explorer XR
		• Explorer XRX
		• Explorer XRX-LRH

- Explorer XRT
 - Explorer XC
 - Explorer XCX
 - Explorer XCX-LRH
 - Explorer XCA
 - Tiger 1200 XR
 - Tiger 1200 XRX
 - Tiger 1200 XRX-LRH
 - Tiger 1200 XRT
 - Tiger 1200 XCX
 - Tiger 1200 XCA
- New calibrations for:**
- Thruxton TFC
- Updated calibrations for:**
- Scrambler 1200 XC
 - Scrambler 1200 XE
- Updated calibrations for:**
- Speed Triple RS
 - Scrambler 1200 XC
 - Scrambler 1200 XE
- New ECU Unlock Codes:** Thruxton TFC - 54091730
- New calibration selection menus added for:
- Bonneville T120 Black
 - Bonneville T120 Ace/Diamond Editions
- Scrambler 1200 Models, keyless ECM download:**
- Fix to ensure that 'Software up to date' messages reference the keyless ECM.
- Speed Triple RS, Immobilizer Diagnostics and Download Connection:**
- Addition of previously unsupported keyless ECM part numbers to diagnostic tool database.
 - Fix resolves keyless ECM Immobilizer Diagnostics and Download connection issues for Speed Triple RS models fitted with keyless ECM part numbers 2502226 and 2502227.

4 **Instrument ECM Calibrations:**5 **Keyless ECM Calibrations:**6 **New ECU Unlock Codes:**7 **Calibration Description Corrections:**8 **Bug Fix(es):**

If you have any questions, please contact Triumph Customer Support at (888) 284-6288.