

# Technical Service Bulletin

93 MIL on, DTC logged for HV battery (GFF indicates battery should be replaced)

93 19 11 2049384/2 April 24, 2019. Supersedes Technical Service Bulletin Group 93 number 17-09 dated November 16, 2017 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
А3	2016 - 2018	All	e-tron
Audi e-tron quattro	2019 - 2020	All	e-tron

#### Condition

REVISION HISTORY				
Revision	Date	Purpose		
2	-	Revised header (Updated documentation, added model years, and model)		
1	11/16/2017	Initial publication		

#### **Customer may report:**

• MIL on.

#### Workshop findings:

- In the battery regulation control module, J840 (address word 008C) or in the high-voltage battery charger control module, J1050 (address word 00C6) a DTC is logged for the HV battery.
- GFF is performed and indicates to replace the HV battery.

### **Technical Background**

Not applicable.

### **Production Solution**

Not applicable.

#### **Service**



## Technical Service Bulletin

- 1. Review and follow the instructions in the **attached document** to ensure correct documentation is performed for any battery repairs.
- 2. Perform classification test plan to determine the state of the battery, for shipping process (critical or non-critical).
- 3. Contact TAC with requested documentation uploaded.
- 4. Complete the attached document after TAC provides direction.

### **Warranty**

This TSB is informational only and not applicable to any Audi Warranty.

#### **Additional Information**

All parts and service references provided in this TSB (2049384) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2019 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.