

Date	Expiration	Release	Page
04.2019	04.2021	1	1(5)

First Release

04-15-2019

BRIGADE CAMERA SYSTEM SETUP AND ACTIVATION

Prevost vehicles

DESCRIPTION

On the vehicles affected by this bulletin, the Brigade camera system parameters must be set up and the system rebooted to enable activation.

MODEL YEAR(S) AND VEHICLES INVOLVED

NOTICE TO SERVICE CENTERS	
Verify vehicle eligibility by checking warranty bulletin status with SAP or via ONLINE WARRANTY SYSTEM available on Service / Warranty tab of Prevost website.	
Model	VIN
H3-45 coaches Model Year : 2019	2PCH33496 <u>KC720550</u> , 2PCH33491 <u>KC720553</u> & 2PCH33494 <u>KC720546</u>
This bulletin does not necessarily apply to all the above-mentioned vehicles, some vehicles may have been modified before delivery.	


PROCEDURE

 DANGER
Park vehicle safely, apply parking brake, stop engine. Prior to working on the vehicle, set the ignition switch to the OFF position and trip the main circuit breakers equipped with a trip button. Lock out & Tag out (LOTO) must be performed during set-up, maintenance or repair activities. Refer to your local procedure for detailed information regarding the control of hazardous energy.

Date	Expiration	Release	Page
04.2019	04.2021	1	2(5)

1. Connect the power cable and MDR (Brigade module) yellow connector.

- Connect a mouse in the MDR front USB port.
- Switch the power ON.



2. Right click on the image that appears on the screen.

- Click on the icon at the bottom (right) of the screen



	Date	Expiration	Release	Page
	04.2019	04.2021	1	3(5)
3. Enter username and password then click the Login button. - Username: admin - Password: admin				
4. Click the SETUP button.				
5. Select the "Basic Setup" top screen tab and click: Reg Info. Vehicle Info. - Write client name - Write VIN number - Click Save to register the data.				
6. Select the "Basic Setup" top screen tab and click: Time Setup. General. - Set the Time Zone - Save				

Date	Expiration	Release	Page
04.2019	04.2021	1	4(5)

7. Select the “**Surveillance**” top screen tab and click:
- Record.**
 - HDD.**
 - For a 4 Cameras system uncheck the box in:



- Repeat the operation for channel # 5, 6, 7 & 8 (Click **SAVE** before switching channels).



8. Select the “**Alarms**” top screen tab and click:
- Video.**
 - Video Loss.**
 - Uncheck Video Loss.
 - Save



9. Select the “**Surveillance**” top screen tab and click:
- Record.**
 - General.**
 - Change Video Format for NTSC-AHD.
 - Click YES to confirm changes.
 - System will reboot.



	Date	Expiration	Release	Page
	04.2019	04.2021	1	5(5)
10. Wait for the display of this screen and shut off the power supply.				

ESTIMATED TIME

The time required to perform this special bulletin is approximately half an hour (0.5h).

OTHER

VBC Bulletin	N/A
Fail Code	23.00
Defect Code	09
Syst. Cond	B
Causal Part	900270

Access all our Service Bulletins on
<http://techpub.prevostcar.com/en/>

or scan the QR-Code with your smart phone.



Prevost engages in a continuous program of testing and evaluating to provide the best possible product. Prevost, however, is not committed to, or liable for updating existing products.