

## LATEST VEHICLE CONCERN FIXES



Check Engine Lamp with DTC P026B	18-19 MY Range Rover and Range Rover Sport equipped with AJ133
<p><b>Customer Voice:</b></p> <ul style="list-style-type: none"><li>- The Check Engine Lamp is on.</li></ul> <p><b>Technical Description:</b></p> <ul style="list-style-type: none"><li>- DTC P026B-00 and injector specific DTC are stored in the PCM.</li><li>- DTC may appear as 185733 Undefined.</li></ul> <p><b>Status:</b></p> <ul style="list-style-type: none"><li>- Inspect the electrical circuit between the PCM and injector including inspection of connectors, pin fit and proper pin tension. If no faults are identified in the circuit, reset the PCM adaptations and perform several road tests. If the DTC persists, replace the fuel injector.</li><li>- Testing of injectors replaced has not yielded replication of the condition. Work instructions to support evaluation on a vehicle exhibiting the condition are being developed and will be provided via a TA.</li><li>- Raise an EPQR for any repairs performed and hold any parts replaced for return. Label any injectors removed using the DIN standard outlined in TOPlx.</li></ul>	

