

# LATEST VEHICLE CONCERN FIXES



PCV Diaphragm Torn	All models equipped with AJ126 or AJ133
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none"><li>- The Check Engine Lamp is illuminated.</li></ul> <p><u>Technical Description:</u></p> <ul style="list-style-type: none"><li>- There is an unmeasured air leak from the PCV valve diaphragm.</li></ul> <p><u>Status:</u></p> <ul style="list-style-type: none"><li>- A lower level repair kit has been developed and can be ordered through parts.</li><li>- Part number is LR133579 / C2D60163.</li><li>- Part will be delivered to the UK warehouses this week.</li><li>- Local sample parts stock has been exhausted, so please do not raise a TA to obtain parts.</li></ul>	<p>The diagram illustrates the PCV valve assembly. Part 9K617B is the upper PCV valve assembly. Part 13B802 is a circular diaphragm seal, shown in a magnified view with red lines indicating its location on the valve. Part 9K617A is the lower PCV valve assembly, which is mounted to the engine block.</p>

