

ATTENTION: Dealer Principal, Warranty Manager, Service Manager, Parts Manager
Freightliner Dealers – U.S. and Canada
Western Star and Sterling Dealers – U.S. and Canada
FCCC Dealers – U.S. and Canada
Direct Warranty Customers – U.S. and Canada
Export Distributors

Daimler Trucks North America LLC

WARRANTY CAMPAIGNS DEPARTMENT

P.O. Box 4090

800-547-0712

Portland, Oregon 97208-4090

If you have questions
about this Letter, please
submit your inquiry on the
Web using the [WSC Link](#)
on DTNACconnect

REF #: ICI19-010

Effective: 03/08/19

Release: 03/08/19

SUBJECT: FL780 Cascadia ICUC Bulb Check Function – Additional Information

This letter is to inform you that an update to the FL780 work instructions are pending release that will include more detailed steps for programming the ICUC. Until the revised bulletin is published, please follow the process steps in Freightliner Service Bulletin 54-308 "Chassis ECU Programming", when performing the programming of the ICUC.

If you have questions or need further information, contact the Warranty Campaigns Department by submitting an inquiry through the WSC Link on DTNACconnect.

The information contained in this letter supercedes and supplements any related policies and procedures in any previously released bulletins, the Warranty Manual, and/or previously released letters. Failure to read or distribute this letter will not exempt addressees from compliance with the information contained herein.