

Service Bulletin

04-060

May 7, 2019 Version 6

Odyssey: PCM Replacement for Erratic or Harsh Shifting

This service bulletin has been cancelled because the time limit has expired.

CUSTOMER INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Honda automobile dealer.