


LATEST VEHICLE CONCERN FIXES



Check Engine Lamp with DTC P026B	18-19 MY Range Rover and Range Rover Sport equipped with AJ133
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none">- The Check Engine Lamp is on. <p><u>Technical Description:</u></p> <ul style="list-style-type: none">- DTC P026B-00 and injector specific DTC are stored in the PCM.- DTC may appear as 185733 Undefined. <p><u>Status:</u></p> <ul style="list-style-type: none">- Inspect the electrical circuit between the PCM and injector including inspection of connectors, pin fit and proper pin tension. If no faults are identified in the circuit, raise a TA for diagnostic support.- We are currently seeking a faulting vehicle at a retailer to fit a logger to in order to gather data to support root cause analysis.	 A detailed 3D CAD rendering of an AJ133 injector. The component is shown at an angle, highlighting its complex mechanical structure, including the nozzle at the bottom, the body, and the electrical connector at the top.

