


# LATEST VEHICLE CONCERN FIXES



Recess Underneath The Seat Cover	RR Velar 18 – 19MY
<p><b>Customer Voice:</b></p> <ul style="list-style-type: none"><li>– A customer may express a concern that a recess can be felt underneath the front and or rear seat covers.</li></ul> <p><b>Technical Description:</b></p> <ul style="list-style-type: none"><li>– Vehicles without heated or climate seats have a recess where the optional parts are installed.</li></ul> <p><b>Status:</b></p> <ul style="list-style-type: none"><li>– TSB LTB01269NAS1 is being published to address this issue, should a customer express a concern by installing a foam pad into the recess underneath the seat cover.</li></ul>	 <p>E245214</p>

