

## LATEST VEHICLE CONCERN FIXES



### Engine Cooling Fan Operates at High Speed

18-19 MY Discovery Sport, RR Evoque, E PACE, F PACE, F TYPE, XE, XF with AJ20P

#### Customer Voice:

- The engine fan is making a lot of noise.
- The engine fan runs after I turn the car off.

#### Technical Description:

- DTC P26CB-72 and/or P2B61-73 are stored in the PCM.

#### Status:

- Perform diagnostic steps outlined in the TOPlx workshop manual 100-00 >Diagnostic Trouble Code Index Ingenium I4 2.0L Petrol > DTC: Powertrain Control Module.
- If no faults are identified with the circuit, replace the coolant pump. Raise an EPQR and provide a name, email address, and phone number of someone who can serve as the point of contact for the shipping company to collect the original sensor.

