

GPOP - Issue Review System

Part Number: 68157611A\$, 68157610A\$

Part Description: CALIPER ASSEMBLY, Disc Brake, Front

Issue Description: For an issue with drift ONLY when braking, please replace the complete front caliper assemblies including adapters and pads as a unit, unbolting them from the knuckle. Also replace both front rotors, labeling right (RT) and left (LT).

Call Mark Randall at (248) 520-3863, if no answer leave a message with last 8 of VIN, dealer code, and mileage. Save the Caliper Assemblies and Rotors for FasTrack return and root cause analysis.

If no response in 15 minutes, proceed with repair.

~

~

Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
