

GPOP - Issue Review System

Part Number: 05057506A\$, 05057507A\$, CSZHT791A\$, CSZHT792A\$

Part Description: Brake Transmission Shift Interlock (BTSI)

Issue Description: Please contact Stacey Davis at (248) 260-6078 or stacey.davis@fcagroup.com if the following scenario occurs;
The T79 or U11 recall was completed where the shifter inspection was acceptable and the software flash was performed but then the customer comes back needing the BTSI bracket replaced for coming out of park without the brake or key.

~
Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system