



**Spartan Chassis Bulletin 18-330-010 – Hadley ECU update**

<b>Bulletin Type:</b>	Technical Service Bulletin TSB	<b>Publication Date:</b>	June 2019
<b>Bulletin #:</b>	19-027	<b>Make:</b>	Entegra
<b>Job Code:</b>	NA	<b>Models:</b>	Anthem Cornerstone
<b>Flat Rate:</b>	NA	<b>Model Year:</b>	2019

<b>Incident/ Repair</b>	Hadley system may be active when the ignition is off. An update to the software by a Spartan Service Center is required.
<b>Affected Units:</b>	<p><b>2019 Anthem</b> K1<u>4A</u>8051-8063 <b>4B</b>8051-8110 <b>4F</b>8051-8114 <b>4H</b>8051-8067 <b>4W</b>8051-8097</p> <p><b>2019 Cornerstone</b> K1<u>6A</u>8051-8056 <b>6B</b>8051-8095 <b>6F</b>8051-8086 <b>6W</b>8051-8090 <b>6X</b>8051-8061 <b>6Y</b>8051-8062</p>

Ways to locate convenient Spartan facility for the Bulletin repair:  
 Spartan Website - [spartanchassis.com/cps/service/service\\_centers.asp](http://spartanchassis.com/cps/service/service_centers.asp)  
 Spartan Toll Free Number - **1-800-543-4277 opt 0**