

Head-up display (HUD) code 463 – lines on the display, display flickers

| | |
|-------------------|--|
| Topic number | LI54.30-P-069742 |
| Version | 2 |
| Function group | 54.30 Instrument cluster, display instruments, hazard warning device |
| Date | 06-18-2019 |
| Validity | Model series 205 with code 809+463 and not 464 Model series 253 with code 809+463 |
| Reason for change | SA code for modification year updated |
| Reason for block | |

Complaint:

The image in the head-up display (HUD) flickers and/or has lines on it. See attachment for details.

| Attachments | |
|---------------------------------|-----------------------------|
| File | Description |
| HUD image quality complaint.jpg | HUD image quality complaint |

Cause:

Signal from instrument cluster (IC entry) to head-up display not within specification.

Remedy:

Please replace the instrument cluster. Do not replace the head-up display.

| Symptoms |
|--|
| Communication/information / Information display / Displays / Head-up display / Function / Contrast/brightness/distortion |
| Communication/information / Information display / Displays / Head-up display / Function / Difficult to read |

| Control unit/fault code | | |
|---|------------|------------|
| Control unit | Fault code | Fault text |
| A40/12 - Head-up display (HUD) (HUD222) (C (205)) | - | - |
| A1 - Instrument cluster (IC) (IC213) (C (205)) | - | - |

| Attachments |
|-------------|
|-------------|

XENTRY TIPS

HUD image quality complaint.jpg:

