

## Air conditioning system heating instead of cooling

---

Topic number	LI83.30-P-068662
Version	3
Function group	83.30 Air conditioning
Date	06-17-2019
Validity	BR 177
Reason for change	New modified parts are available
Reason for block	

---

### Complaint:

The air conditioning system is blowing hot instead of cooling

### Cause:

Possible cause:

Temperature sensor in overhead control panel (OCP) may be delivering incorrect values.

To confirm the root cause, set the air conditioning system to MAX cold. If the output is now cold, then the temperature sensor in the OCP is at fault.

### Remedy:

In the event of complaints, replace overhead control panel. The part number can be found in XPPI Group 82, Sub-group 172, Position 10.

<b>Symptoms</b>
Body / Air conditioning / Air conditioning / Insufficient cooling output

Operation numbers/damage codes				
Op. no.	Operation text	Time	Damage code	Note
			83403 73	