

L625-
A.01.19

To: **Official After Sales Network**
Subject: **Soft top capote hinges replacement**
Date: **05 April 2019**
Pages: **3**



Campaign code.

L625-A.01.19

Campaign name.

Soft top capote left and right hinges replacement

Model.

Huracàn

Model year.

MY 18

Special or Limited editor.

Spyder

Markets.

NAR and Europe

VIN identification.


From JLA10115 to JLA10375

..JLA10115	.. JLA10206	.. JLA10243	.. JLA10299
.. JLA10151	.. JLA10208	.. JLA10249	.. JLA10305
.. JLA10161	.. JLA10214	.. JLA10251	.. JLA10307
.. JLA10167	.. JLA10216	.. JLA10263	.. JLA10315
.. JLA10169	.. JLA10219	.. JLA10265	.. JLA10332
.. JLA10181	.. JLA10230	.. JLA10278	.. JLA10335
.. JLA10184	.. JLA10234	.. JLA10291	.. JLA10375
.. JLA10194	.. JLA10242	.. JLA10293	..

Important: before starting with the repair, log to the Warranty portal and check through VIN Info:

- The vehicle is effectively involved by these bulletin instructions; some cars may not be included even when they are in the VIN range.
- The procedure identified by a letter (e.g. A, B or C...etc. whose differences are explained below in this bulletin), taking care to order and use the parts corresponding to the assigned procedure.

Example



Note:

Procedure A will be available only when the instructions require to carry out a preliminary control to determine whether or not a vehicle needs to be updated.

Information to the field:

As a result of continuous product monitoring, Automobili Lamborghini Spa has found a possible problem in the hinges of the soft top capote.

Solution for the network:

Follow the instructions below to replace the soft top capote hinges.



The above picture is only for explicative purposes.

L625-
A.01.19

To: **Official After Sales Network**
Subject: **Soft top capote hinges replacement**
Date: **05 April 2019**
Pages **3**



Spare parts:

Order the following part number which are connected to the operation required:

- Operation B – Soft top capote left and right hinges replacement

P/N	Description	Q
4T7898021	Tonneau cover latch left	1
4T7898022	Tonneau cover latch right	1

Replaced parts management.

Store properly and tagged the parts replaced with bar code form for their identification during Area Manager visits.

Labour time

- Operation B: 1.7 h


Substituted former Bulletins.

None.

Warranty Claim instructions

To claim the reimbursement log into the warranty system management on the Lamborghini Portal and consults the manual “W.Claim “ available on the portal for the download .

Select the desired campaign and go on with the claim insertion, read carefully the windows message content and choose the option button corresponding to the operation performed .



On the base of the chosen option the reimbursement will be:

- OPTION B – Soft top capote left and right hinges replacement
manpower: 1.7 h.
spare parts: 4T7898021 & 4T7898022.



ATTENTION!

Attach all documents produced during the vehicle visit that show evidence of the work performed such as repair order, software protocols or acquisitions...etc.; the lack of one or more of those, may deny the reimbursement.

Remember to fill all data in the section “Service and Recall Campaign” in the Warranty booklet of the vehicle as shown below.

**L625-
A.01.19**

To: Official After Sales Network
Subject: Soft top capote hinges replacement
Date: 05 April 2019
Pages 3



Technical procedure

Herein is provided a link which refers to the workshop manual for the replacement of the left and right hinges of the soft top capote of the Huracàn Spyder.

Therefore, login on the workshop manual and follow the below paths which will lead to the complete procedure.

Left latch

Workshop manual → Huracan Spyder → 08 Body → 71
Soft top → AM Complete Tonneau Cover Left Latch →
Disassembly/Assembly.

Right latch

Workshop manual → Huracan Spyder → 08 Body → 71
Soft top → AN Complete Tonneau Cover Right Latch →
Disassembly/Assembly.

For further information, please contact Technical Support.