

IMPORTANT: EMISSION RECALL REMINDER

In May 2018, we notified you of an Emission Recall involving the EVAP canister charge hose on your 2017 or 2018 CMX300/A or CMX500/A - Rebel motorcycle. At the time, we advised owner's of the following:

Honda has determined that a defect related to emissions regulations exists in all model 2017 and certain model 2018 Honda CMX300/A and CMX500/A - Rebel motorcycles. The fuel vapor permeation of the EVAP canister charge hose exceeds the federal permeation standards. An updated part, made of a different material, is available to correct this condition.

According to our records, you have not yet had your affected motorcycle repaired. Please call your authorized Honda motorcycle dealer to schedule an appointment as soon as possible. This recall repair will be performed free of charge.

If your motorcycle has already been repaired, or if you no longer own this motorcycle, please let us know by filling out the included, postage paid, *Information Change Card*. We will update our records and stop sending you reminder notices.

If you have any questions about this recall, your authorized Honda motorcycle dealer will be happy to assist you.

Sincerely,

**American Honda Motor Co., Inc.
Powersports Products**

MTB 17252 (1907)