

Release date:

7/23/2019

Condition

Applicable Vehicles						
Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To	
All Except Routan	2012 - 2019	All	All	All	All	

Revision Table						
Instance Number	Published Date	Version Number	Reason For Update			
2035473/10	7/23/19	91-17-01	To include 2018 and 2019 model year applicability and modify verbiage pertaining to submission requirement.			
2035473/9	2/16/17	V911701	To include 2017 model year applicability.			
2035473/1	11/7/13	V911323	Original publication.			

Technical Background

This bulletin provides instructions and information for completing and submitting the updated web version of the Infotainment Worksheet. Like the previous version, the Infotainment Worksheet allows more detail to be provided for repairs related to the Infotainment System (radio, navigation, Bluetooth, telephone systems, etc.). The new web version provides an easier approach by which to complete and submit the information.

Because of advanced and frequently changing technology, it is critical that detailed information is provided in order to better understand issues related to Infotainment.

One or more of the following symptoms are possible, but not limited to:

- Poor AM/FM/Satellite radio reception.
- Poor sound quality.
- Inability/difficult to pair phones, phone loses pairing.
- Navigation system malfunctions or is inoperative.
- Car-Net system malfunctions or is inoperative.
- Rearview Camera malfunctions or is inoperative.
- · Radio or Navigation display issues.
- Poor sound quality during phone calls.





Transaction No: 2035473/10

Release date: 7/23/2019

- CD player/changer malfunctions or is inoperative.
- Voice command(s) malfunctions or is inoperative.

Production Solution

Not applicable.

Service



Refer to Elsa for other Technical Bulletins that may apply to specific vehicles with customer complaints related to the Infotainment System. These Technical Bulletins provide important information about vehicle and/or component specific issues.

If diagnosis leads to the repair or replacement of one or more component(s) in the Infotainment System, complete the Infotainment Worksheet. The Infotainment Worksheet can be accessed by clicking the appropriate link on the VW Hub (figure 1).



Figure 1



Release date: 7/23/2019

An additional link to the form is also available on Service Net (figure 2).





Figure 2





Release date: 7/23/2019

Once the form is opened, please fill in all the applicable information related to the repair. Click the "Submit Infotainment Report" button at the bottom of the form once completed. Once the form has been submitted, no further action is required and another form can be completed if necessary (Figure 3).



Figure 3





Release date: 7/23/2019

2035473/10

Transaction No:

Warranty

Information only.

Required Parts and Tools

No Special Parts required.

No Special Tools required.

Additional Information

All part and service references provided in this Technical Bulletin are subject to change and/or removal. Always check with your Parts Dept. and Repair Manuals for the latest information.