



Bulletin No.: PIC6369

Published date: N/A

# Preliminary Information

## PIC6369 Front Park Assist Indicates Object Detected When In A Reverse Turn With Wheels Turned At Or Near Lock

### Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Cadillac	CT6	2016 - 2017	ALL	ALL	ALL	ALL

Involved Region or Country	North America
Additional Options (RPO)	With 20 Inch Wheels 5JO, RQ9, RQA, SHH
Condition	Some customers may comment that while in a reverse turn with the steering wheel turned at or near lock the front park assist indicator will appear and indicate an object detected.

### Correction:

After a thorough engineering review, this has been determined to be an operational characteristic on vehicles equipped with 20 inch wheels. Do not attempt any repairs.

Please communicate to the customer this condition is a normal operating characteristic of their vehicle. Please share this information with the customer, including a copy of this message.

**Note: This PI may be converted into a bulletin when new information is available.**

### Version History

Version	1
Modified	07/24/2019 - Created on.



GENERAL MOTORS