


Latest Vehicle Concern Fixes



Steering Wheel Off Center	2019 Range Rover Velar
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none">• Customer states the steering wheel is off center. <p><u>Technical Description:</u></p> <ul style="list-style-type: none">• The steering wheel is found to be off center at low time in service or during the PDI. <p><u>Status:</u></p> <ul style="list-style-type: none">• This is currently under investigation.• Please submit an EPQR with pictures of the position of the steering wheel as well as the before and after specs from the alignment.	 A photograph of the interior of a 2019 Range Rover Velar, focusing on the steering wheel and dashboard. The steering wheel is black with silver accents and the Range Rover logo in the center. The dashboard features a digital display showing the speedometer and other vehicle information. The car is parked in a lot with other vehicles visible in the background.

