

Latest Vehicle Concern Fixes



Telematics Control Unit Software Download Performance

Customer Voice:

- TCU_3 Programming failures

Technical Description:

- TCU_3 software download incomplete due to software iteration step

Status:

- Software download failure is only present on LG TCU_3 vehicles
- Please follow TOPIx Workshop Manual Guided Flow for TCU diagnosis.
 - 415-01
- Pathfinder software download logic will be implemented by end of June.
 - Including replacement of TCU module if the software is at an old level

18MY – 20MY E-PACE, F-PACE, I-PACE, F-TYPE, XE, XF, XJ, Range Rover, RR Sport, RR Velar, RR Evoque, Discovery, Discovery Sport

ECU Diagnostics Telematic Control Unit Module [TCU]

▲ Software Download did not complete

Software download status			
Current vehicle information	Latest software information	DID	Status
J8A2-70712-DS	J8A2-70712-DS	F121	Update Successful
J8A2-70712-FR	J8A2-70712-FS	F122	Update Failed
J8A2-70712-GK	J8A2-70712-GK	F123	Update Successful
J8A2-70712-AR	J8A2-70712-AS	F188	Update Failed
J8A2-70712-BS	J8A2-70712-BS	F120	Update Successful
J7A3-70713-BR	J7A3-70713-BS	F124	Update Failed
J7A3-70713-JR	J7A3-70713-JS	F125	Update Failed

