


Latest Vehicle Concern Fixes



No Start Due To BCM	2018-2019 Range Rover Range Rover Sport & Velar
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none">• Customer states the vehicle will not start. <p><u>Technical Description:</u></p> <ul style="list-style-type: none">• The door locks operate correctly but, when the start/stop button is pressed the vehicle does not start due to the BCM. <p><u>Status:</u></p> <ul style="list-style-type: none">• This is currently under investigation. If you should come across this issue, please submit an EPQR.	 A photograph of a black plastic Body Control Module (BCM) component. It is a rectangular unit with several electrical connectors and ports on its surface, including a large multi-pin connector at the top and a smaller one at the bottom. The component is shown against a plain white background.

