



Preliminary Information

PIT4204A CJ2 HVAC Recirculation Door Operation in Manual Mode Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Buick	Rainier	2004 - 2008	All	All	All	All
Chevrolet	Trailblazer	2002 - 2009	All	All	All	All
Chevrolet	Trailblazer EXT	2002 - 2009	All	All	All	All
GMC	Envoy	2002 - 2009	All	All	All	All
GMC	Envoy XL	2002 - 2009	All	All	All	All
GMC	Envoy EXV	2002 - 2009	All	All	All	All
Oldsmobile	Bravada	2002 - 2004	All	All	All	All
Saab	97x	2005 - 2008	All	All	All	All

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition / Concern

While operating the CJ2 Automatic HVAC in manual mode, bi-level or vent, some customers may comment that the recirculation mode will not stay ON for longer than 10 minutes and/or default to the OFF position after the ignition is cycled from On to Off and back On again.

Recommendations / Instructions

This is the normal operation of the CJ2 automatic HVAC system and no parts should be replaced.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.



GENERAL MOTORS