

Subject

Navigation Voice Prompts and Feedback Beeps Inoperative

Market

USA

Service Category

Audio/Visual/Telematics

Section

Navigation/Multi Info Display

Applicability

2019 Highlander and Highlander HV

APPLICABLE VEHICLES

2019	Highlander	2019	Highlander HV
------	------------	------	---------------

CONDITION

Voice navigation prompts and feedback beeps are inoperative after starting the engine. This condition only occurs on Platinum grade vehicles.

RECOMMENDATIONS

Note: This Tech Tip is no longer applicable, and all previous versions should be discarded.

Follow T-SB-0042-19 for the latest information.

LINK REFERENCES

This Tech Tip does not contain any link references